

CLASSIFIED MESSAGE

MFG. 5-33

Approved For Release 2002/10/24 : CIA-RDP67B00820R000200030014-6

DATE 1309Z 26 FEB 64

S E C R E T

ROUTING

2	CD	9	RB
3	"	10	Intel
4	DT-gh	11	
5		12	
6		13	
7	Idea	14	
8	DISA	15	
		16	

TO : DIRECTOR

FROM : 25X1A

ACTION:

INFO : OSA 1-15

ROUTINE

TOR 1632Z 26 FEB 64

IN 64627

25X1A

TO

INFO

CITE

8256

LOGS

25X1A

REF: TELECON 2/25/64 25X1A

25X1A

1. RE DAYTON PROBLEM, MY UNDERSTANDING IS THAT DAYTON AT IS LEAKING AND SHOULD BE REPAIRED. MODEL 3 PROCESSOR NOW IN SHIPMENT TO WILL SUBSTITUTE FOR DAYTON IF DESIRED AS WILL VERSAMAT WHEN DELIVERED.

25X1A

2. WE ARE PROCEEDING TO OVERHAUL DAYTON RECENTLY RETURNED FROM FOR IN-HOUSE USE IF NO OTHER NEED IS FOUND. BECAUSE WE WERE EXPECTING TWO DAYTONS FOR OVERHAUL, WE HAVE MADE TWO SETS OF PARTS.

25X1A

3. DAYTON DESTINED FOR IS IN BOX 19 OF SHIPMENT. IT IS COMPLETE EXCEPT FOR MAIN ELECTRICAL CONNECTOR WHICH WAS LEFT HERE. SUGGEST YOU TAKE CONNECTOR OFF BARKSDALE MACHINE NOW AT AND USE. THIS CONNECTOR IS YOUR PROPERTY NOT BARKSDALES. WE WILL SEND NEW MANUAL ON MODIFIED DAYTON TO

25X1A

25X1A

25X1A

4. IT IS MY UNDERSTANDING YOU WILL GIVE US AN ORDER FOR A

S E C R E T

GROUP 1
Excluded from automatic
downgrading and
declassification

3

25X1A

☐ 8256 (IN 64627)

S E C R E T

PAGE TWO

25X1A

25X1A

COMPLETE NEW VERSAMAT FOR ☐ SINCE WE ARE WORKING ON ONE FOR ☐ AND MACHINES ARE IN SHORT SUPPLY, IT WOULD BE TO YOUR ADVANTAGE IN BOTH TIME AND MONEY TO PLACE THIS ORDER ASAP.

25X1A

25X1A

5. FOLLOWING DELIVERY OF VERSAMAT TO ☐ IT IS MY ^{25X1A} UNDERSTANDING YOU WILL SHIP DAYTON NOW IN BOX 19 TO ☐ AND ^{25X1A} RETURN THE DAYTON NOW AT ☐ EITHER TO US OR TO THE DEPOT FOR STORAGE. WE WILL STORE THE SECOND SET OF DAYTON PARTS AGAINST EVENTUAL USE IN OVERHAULING THIS MACHINE. BE SURE THAT DAYTON NOW AT ☐ IS THOROUGHLY CLEANED AND DRIED BEFORE STORAGE.

END OF MESSAGE

S E C R E T